

國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

| 編號 No. | 單位名稱 The name of the organization | 地點 Location of installation | 大腸桿菌群 Coliform | 採樣日期 Collection Date | 檢測結果 Test results |
|---|--|---|-------------------|-------------------------|----------------------|
| 一、國立清華大學新竹市東區光復路2段101號 National Tsing Hua University No. 101, Section 2, Guangfu Road, East District, Hsinchu City | | | | | |
| 1 | 台積館 TSMC Building | 五樓茶水間 5F Pantry Room | <1 | 113/4/10 | |
| 2 | 清華實驗室(220V) Tsing Hua Laboratory(220V) | 2F茶水間 Pantry Room | <1 | 113/4/10 | |
| 3 | 清華實驗室(220V) Tsing Hua Laboratory(220V) | 7F茶水間 Pantry Room | <1 | 113/4/10 | |
| 4 | 綠能教學大樓 Green Energy Research and Education Building (Lee Tsen Min Building) | 1F茶水間 Pantry Room | <1 | 113/4/10 | |
| 5 | 綠能教學大樓 Green Energy Research and Education Building (Lee Tsen Min Building) | 5F茶水間 Pantry Room | <1 | 113/4/10 | |
| 6 | 綜二大樓教務處 General Building II : Office of Academic | 1F茶水間 Pantry Room | <1 | 113/4/10 | |
| 7 | 綜二大樓天文所 General Building II : Institute of Astronomy | 5F茶水間 右Pantry Room (Right) | <1 | 113/4/10 | |
| 8 | 綜三大樓理學院 General Building III : College of Science | 4F辦公室旁 Next to the office | <1 | 113/4/10 | |
| 9 | 物理館 Physics Building | 7F(男廁旁 Next to the men's room) | <1 | 113/4/10 | |
| 10 | 化學館 Department of Chemistry | 5F | <1 | 113/4/10 | |
| 11 | 清華幼稚園 Tsing Hua Kindergarten | 東院10號(1) East Yuan Faculty Residences No.10 (1) | <1 | 113/4/10 | |
| 12 | 育成中心 Center of Incubator | 1F | <1 | 113/4/10 | |
| 13 | 育成中心 Center of Incubator | 4F | <1 | 113/4/10 | |
| 14 | 誠齋(Dorm Cheng) | 1樓電梯東(East side of the elevator on the 1st floor) | <1 | 113/4/10 | |
| 15 | 學齋(Dorm Shiu) | B棟(Building B) 7樓(7th floor) | <1 | 113/4/10 | |
| 16 | 學齋(Dorm Shiu) | A棟(Building A) 1樓104(1st floor 104) | <1 | 113/4/10 | |
| 17 | 清齋(Dorm Tsing) | D棟(Building D) 1樓洗衣間(Laundry room on the 1st floor) | <1 | 113/4/10 | |
| 18 | 清齋(Dorm Tsing) | C棟(Building C) 101旁會議室(Meeting room next to the | <1 | 113/4/10 | |
| 19 | 碩齋(Dorm Shuo) | 2樓202旁(Next to 202 on the 2nd floor) | <1 | 113/4/10 | |
| 20 | 儒齋(Dorm Ru) | D棟(Building D) 3樓(3rd floor) | <1 | 113/4/10 | |
| 21 | 慧齋(Dorm Hwei) | 1樓廚房(1st floor kitchen) | <1 | 113/4/10 | |
| 22 | 新齋(Dorm Ksin) | 5樓A區(Area A, 5th floor) | <1 | 113/4/10 | |
| 23 | 新齋(Dorm Hsin) | 1樓管理員室(Administrator's room on the 1st floor) | <1 | 113/4/10 | |
| | 以下空白 | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

符合規定 in compliance with regulations



國立清華大學水質檢驗結果一覽表 National Tsing Hua University Water Quality Inspection List

| 編號 No. | 單位名稱 The name of the organization | 地點 Location of installation | 大腸桿菌群 Coliform | 採樣日期 Collection Date | 檢測結果 Test results |
|--|--------------------------------------|--|-------------------|-------------------------|---|
| 二、國立清華大學南大校區 新竹市東區大路521號 National Tsing Hua University Nanda Campus No. 521 Nanda Road, East District, Hsinchu City | | | | | |
| 1 | 行政大樓-2-F茶水間 | Administration Building-2F-Tea Room | <1 | 113/4/10 | 符合規定 in compliance with regulations |
| 2 | 藝設系大樓-4F-電梯邊 | Art and Design Building-4F-beside elevator | <1 | 113/4/10 | |
| 3 | 樹德樓-1F-洗衣機旁 | Shu Te Dorm-1F-beside washing machine | <1 | 113/4/10 | |
| 4 | 樹德樓-4F-洗衣機旁 | Shu Te Dorm-4F-beside washing machine | <1 | 113/4/10 | |
| | 以下空白 | | | | |

註1.飲用水水質標準 Note 1. Drinking water quality standards
大腸桿菌群 Coliform : 6 (CFU/100mL)

